USAARL Report No. 94-45





Laboratory and Flight Tests of Medical Equipment for Use in U.S. Army MEDEVAC Helicopters (Reprint)

By

James E. Bruckart Joseph R. Licina Martin D. Quattlebaum



Aircrew Protection Division

94-32714

August 1994

94

)

Approved for public release; distribution unlimited.

United States Army Aeromedical Research Laboratory Fort Rucker, Alabama 36362-0577

Notice

Qualified requesters

Qualified requesters may obtain copies from the Defense Technical Information Center (DTIC), Cameron Station, Alexandria, Virginia 22314. Orders will be expedited if placed through the librarian or other person designated to request documents from DTIC.

Change of address

Organizations receiving reports from the U.S. Army Aeromedical Research Laboratory on automatic mailing lists should confirm correct address when corresponding about laboratory reports.

Disposition

Destroy this document when it is no longer needed. Do not return it to the originator.

Disclaimer

The views, opinions, and/or findings contained in this report are those of the author(s) and should not be construed as an official Department of the Army position, policy, or decision, unless so designated by other official documentation. Citation of trade names in this report does not constitute an official Department of the Army endorsement or approval of the use of such commercial items.

Reviewed:

KEVIN T. MASON

LTC, MC, MFS

Director, Aircrew Protection Division

Chairman Scientific

Review Committee

Released for publication:

DENNIS F. SHANAHAN

Colonel, MC, MFS

Commanding

SECURITY CLASSIFICATION OF THIS PAGE						
REPORT (OCUMENTATIO	N PAGE			Form Approved OMB No. 0704-0188	
1a. REPORT SECURITY CLASSIFICATION Unclassified		1b. RESTRICTIVE	MARKINGS			
2a. SECURITY CLASSIFICATION AUTHORITY		3. DISTRIBUTION	Y/AVAILABILITY O	F REPORT		
2b. DECLASSIFICATION / DOWNGRADING SCHEDULE		Approved for public release, distribution unlimited				
4. PERFORMING ORGANIZATION REPORT NUMBE	R(S)	5. MONITORING	ORGANIZATION R	EPORT NU	JMBER(S)	
USAARL Report No. 94-45						
6a. NAME OF PERFORMING ORGANIZATION U.S. Army Aeromedical Research	6b. OFFICE SYMBOL (If applicable)		ONITORING ORGA			
Laboratory	SGRD-UAD-IE	U.S. Army Medical Research, Development, Acquisitions and Logistics Command				
6c. ADDRESS (City, State, and ZIP Code)		7b. ADDRESS (C	ity, State, and ZIP			
P.O. Box 620577 Fort Rucker, AL 36362-0577		Fort Det Frederic	ck, MD 2170	2-5012		
8a. NAME OF FUNDING/SPONSORING ORGANIZATION	8b. OFFICE SYMBOL (If applicable)	9. PROCUREMEN	IT INSTRUMENT ID	ENTIFICAT	ION NUMBER	
8c. ADDRESS (City, State, and ZIP Code)		10. SOURCE OF	FUNDING NUMBER	RS		
		PROGRAM ELEMENT NO.	PROJECT NO.	TASK NO.	WORK UNIT	
		62787A	0162787A878	1	131	
11. TITLE (Include Security Classification) Laboratory and Flight Tests of Helicopters 12. PERSONAL AUTHOR(S)	Medical Equipm	ent for Use	in U.S. Army	y MEDEV	'AC	
James E. Bruckart, Joseph R. L						
13a. TYPE OF REPORT 13b. TIME CO Final FROM	OVERED TO	14. DATE OF REPO	ORT (<i>Year, Month,</i> st	Day) 15.	. PAGE COUNT 6	
16. SUPPLEMENTARY NOTATION Reprinted from <u>Air Medical Journal Control of the Air Medical Journal of the Air Medical Office of the Air Medical Off</u>	rnal, March 199	3, pages 51-	56			
17. COSATI CODES	18. SUBJECT TERMS (Continue on rever	se if necessary and	identify L	by block number)	
FIELD GROUP SUB-GROUP	medical equipmedical electromagnet			cal tra	nsport,	
06 12 20 14	electiomagnet.	ic interfere	ence, salety			
When used in an air medical setting, m in-flight use, or they interfere with critical devices, including monitor/defibrill incubators, were tested under extreme 810D). Electromagnetic emissions and tors were evaluated. The devices were medical devices failed at least one envi interference standards. Failures include emissions. Five (15 percent) of the detection is critical to discover the ability environment. Failure of a device or interference standards.	edical equipment desical rotor-wing aircolators, infusion pure conditions of temped susceptibility were effight tested in a Uronmental test, and ed excess conducted vices were judged up of a medical device terference with airconditional rotors.	esigned for use raft systems. Inps, vital-signs erature, humide measured (MIH-60 MEDEVIDE of and radiated insuitable for use to perform in raft systems call. ABSTRACT SE Unclassifi	From January 1 monitors, vent ity, altitude and IIL-STD 461C VAC helicopter the devices fair emissions and use in the UH-6 n the harsh rote in result in loss	989 to J ilators a d vibratic AND 46 Thirty led to m suscepti of MEDI or-wing of a pat	June 1992, 34 med- and infant transport on (MIL-STD 62), and human fac- y-two percent of the neet electromagnetic ibility to radiated EVAC helicopter. MEDEVAC tient or aircrew.	
22a. NAME OF RESPONSIBLE INDIVIDUAL Chief, Science Support Center		22b. TELEPHONE (205-255-((Include Area Code 5907		FICE SYMBOL RD-UAX-SI	
DD Form 1473 IIIN 26	Previous aditions are	<u> </u>			ATION OF THE BAGE	

Laboratory and Flight Tests of Medical Equipment for Use in U.S. Army Medevac Helicopters

■ James E. Bruckart, MD, MPH, MC; Joseph 🖟 👫 🗃 a, MSS; and Martin Quattlebaum, BS

When used in an air medical setting, medical equipment designed for use in hospitals can fail from the stresses of in-flight use, or they interfere with critical rotor-wing aircraft systems. From January 1989 to June 1992, 34 medical devices, including monitor/defibrillators, infusion pumps, vital-signs monitors, ventilators and infant transport incubators, were tested under extreme conditions of temperature, humidity, altitude and vibration (MIL-STD 810D). Electromagnetic emissions and susceptibility were measured (MIL-STD 461C and 462), and human factors were evaluated. The devices were flight tested in a UH-60 MEDEVAC helicopter. Thirty-two percent of the medical devices failed at least one environmental test, and 91% of the devices failed to meet electromagnetic interference standards. Failures included excess conducted and radiated emissions and susceptibility to radiated emissions. Five (15%) of the devices were judged unsuitable for use in the UH-60 MEDEVAC helicopter. Testing is critical to discover the ability of a medical device to perform in the harsh rotor-wing MEDE-VAC environment. Failure of a device or interference with aircraft systems can result in loss of a patient or aircrew.

Key Words: medical equipment, MEDEVAC, air medical transport, electromagnetic interference, safety

Modern medical equipment significantly improves the medical team's ability to monitor and treat the critically ill patient in the hospital and during transport. These machines routinely pump fluids, assist respirations, monitor heart beats and blood pressure, or keep an infant warm. The sudden failure of a medical device can endanger the lives of patients. In addition, in air medical transports, if a medical device interferes with an aircraft's systems, the fate of the aircraft and the lives of the crew and patient are threatened.

The U.S. Army operates a fleet of helicopters worldwide. More than 500 of these helicopters are designated for medical evacuation tasks (MEDEVAC) during mobilization. However, even in peacetime, Army

units can perform medical evacuations daily. These include missions to support local disaster plans, military training operations, Military Assistance to Safety and Traffic (MAST) programs, and the general military health care system.

Environmental Hazards

Most medical equipment is designed for use in the hospital environment and is rarely designed to withstand the rigors of transport. In air medical transport, these rigors include extremes of temperature and humidity, vibration and shock, and altitude exposure. The U.S. Army has developed standards to define the extremes of temperature, humidity and vibration that a medical device might be exposed to during its operational life. The Army publication "Environmental Test Methods and Engineering Guidelines" (MIL-STD-810D) details the specific requirements for testing air medical equipment.1

Electromagnetic Compatibility

More than 50 years ago, the U.S. Army discovered that the ignition system of military vehicles interfered with communications receivers. This instigated the practice of setting standards to measure and

Maj. James E. Bruckart, MD, MPH, MC, is a U.S. Army flight surgeon and chief of the Life Support Equipment Branch, Biodynamics Research Division, U.S. Army Aeromedical Research Laboratory, Fort Rucker, Ala. Joseph R. Lincina, MSS, and Martin Quattlebaum, BS, also work at the U.S. Army Aeromedical Research Laboratory at Fort Rucker.

A-1,20

suppress electromagnetic emissions to prevent electromagnetic interference.²

Electromagnetic interference in aircraft comes from a variety of sources: transmitters of radio frequencies, including those on the aircraft for HF. UHF. or VHF communication and those on the ground for FM radio or VHF television broadcasts; aircraft power line (400 Hz) electrical and magnetic fields: computer and avionics timing and control circuits that generate radio frequencies of 1 MHz or higher; aircraft power regulators; electrical switching transients from turning on and off aircraft lights, fans, or flaps; and electrostatic discharges, including lighting.3 These transients and electromagnetic waves may transfer into wiring and cause electromagnetic interference to other aircraft systems or medical equipment used in the aircraft.

Currently, equipment that is being considered for procurement by the U.S. government is tested for electromagnetic compatibility in accordance with standards established by MIL-STD-461C, "Electromagnetic Emission and Susceptibility Requirements for the Control of Electromagnetic Interference," and MIL-STD-462, "EMI Characteristics, Measurement of."4.5

This paper describes the results of medical device environmental and electromagnetic compatibility tests for 34 medical devices examined from January 1989 to June

Table 1

Environmental Tests and Methods*

ionniciae rode and n	1011000			
Altitude Test	Operate device at 15,000-feet altitude equivalent for 1 hour			
High-Temperature Test (Operating)	Operate device at 49° C (120° F) for 2 hours			
High-Temperature Test (Storage)	Store device at 63° C (145° F) for 1 hour, 71° C (159° F) for 4 hours, and 63° C for 1 hour			
Low-Temperature Test (Operating)	Operate device at 0° C (32° F) for 2 hours			
Low-Temperature Test (Storage)	Store device at -46° C (-114° F) for 6 hours			
Vibration Test	Vibration for 1 hour in each axis with signature equivalent to helicopter seat			
Humidity Test	Operate device at 30° C (86° F), 95% relative humidity for 4 hours			
*In accordance with M	411 -STD-810D3			

1992. The results of these tests are used by the U.S. Army to determine which medical devices are suitable for use in Army aircraft.

Materials and Methods

The U.S. Army program for testing and evaluating equipment for air medical operations was established for the equipment's use on Army MEDEVAC aircraft. A medical device is tested at the direction of the Army medical department combat developer or materiel developer. First, each candidate medical device is examined to determine how it functions, including examination of electrical safety and battery life. Next, a human factors review is

completed; this includes checks of the visual displays, controls, maintainability, conductors, fasteners, test points, test equipment, fuses and circuit breakers, labels and coding, and safety of the device.

In the next phase of testing, each medical device is evaluated to determine its compatibility and performance in various temperature, altitude and humidity environments (see Table 1).

Electromagnetic compatibility characteristics are determined by testing each medical device in a computer-controlled electromagnetically shielded test chamber. First, while the device is operated, the electromagnetic field strength around the device is measured to determine the amount of electromagnetic energy conducted and radiated by the device. Next, the medical device is exposed to conducted and radiated electromagnetic fields to see if the device will malfunction when exposed to electromagnetic energy. The minimum field strength that leads to failure of the device is recorded for each narrow frequency band in the electromagnetic spectrum.6 The electromagnetic characteristics tests are detailed in Table 2.

Table 2

Electromagnetic Characteristics Tests*

Radiated Emissions (RE) Assess maximum radiated emissions

from 12 kHz to 12.4 GHz

Radiated Susceptibility (RS) Assess tolerance to radiated

electric fields from 10 kHz to 10 GHz

Conducted Emissions (CE) Assess maximum conducted emissions

from 10 kHz to 50 MHz

Conducted Susceptibility (CS) Assess tolerance to conducted electrical energy from 10 kHz to 400 MHz

"In accordance with MIL-STD-461C and MIL-STD-4624.5




Figure 1. U.S. Army UH-60 Black Hawk helicopier, used for air medical transport.

If the medical device performs properly in laboratory testing and does not produce strong electromagnetic fields within specific frequency bands, the device is approved for limited flight tests. During flight tests, the medical device is operated by a military physician in a UH-60 Black Hawk helicopter (Fig. 1). During these tests, every aircraft system is operated while the device is in service to ensure that it does not interfere with the aircraft's systems or that the aircraft's systems do not interfere with the medical device.

Results

From January 1989 to June 1992, 34 medical devices completed laboratory and flight tests at the U.S. Army Aeromedical Research Laboratory. These included cardiac monitor/defibrillators, infant transport incubators, IV infusion pumps, suction pumps, blood pressure monitors and ventilators.

None of the medical devices failed the electrical safety evaluation. At least one human factor deficiency was noted in 17 (50%) of the medical devices tested. The most common deficiencies were the absence of circuit breakers and the absence of the medical devices.

sence of illumination controls for the display.

Table 3 details the number and percentage of medical devices that failed in environmental tests. Eleven (32%) of the medical devices failed at least one of the environmental tests. This included three failures in the altitude chamber, four failures in each of the high-temperature and low-temperature operation tests, and two failures in the high-humidity environment. As a group, none

of the medical devices failed as a result of exposure to vibration.

Table 4 details the number and percentage of medical devices that failed electromagnetic characteristics tests. Thirty-one (91%) of the medical devices failed at least one of the tests. None of the devices failed the conducted susceptibility tests and the mechanical ventilators passed all electromagnetic characteristic tests.

Among the 34 medical devices tested during the past three years, five devices (15%) were found unfit for use in U.S. Army medical evacuation helicopters: three IV infusion pumps, a suction pump and a blood pressure monitor.

Discussion

Failure of IV infusion pumps in the altitude chamber was typically caused by air bubbles in the administration set. This frequently produced an "air-in-line" alarm and the unit would revert to a keep-vein-open (KVO) infusion rate. High-temperature problems in the transport incubators were caused by improperly calibrated "high temp" alarms; these failed to respond when the incubator temperature exceeded set temperature. One defibrillator model would not synchronize to the

Table 3 Number and Percentage of Medical Devices Failing Individual Environmental Tests						
Type of Device	Altitude	Hìgh Temp	Low Temp	Humidity	Vibration	
Infusion Pump (n=7)	3 (43%)	1 (14%)	0	1 (14%)	0	
Monitor/Defibrillator (n=6)	0	1 (17%)	0	1 (17%)	0	
Blood Pressure Monitor (n=5)	0	0	0	0	0	
Suction Pump (n=3)	0	0	1 (33%)	0	0	
Pulse Oximeter (n=3)	0	0	1 (33%)	0	0	
Infant Transport Incubator (n=3)	0	2 (67%)	2 (67%)	0	0	
Ventilator (n=2)	0	0	0	0	0	
Miscellaneous (n=5)	0	0	0	0	0	

Number and Percentage of Medical Devices Failing Electromagnetic Characteristics Tests						
Type of Device	Radiated Emissions	Radiated Susceptibility	Conducted Emissions	Conducted Susceptibilit		
Infusion Pump (n=7)	7 (100%)	0	4 (57%)	0		
Monitor/ Defibrillator (n=6)	5 (83%)	4 (67%)	4 (67%)	0		
Blood Pressure Monitor (n=5)	5 (100%)	2 (40%)	5 (100%)	0		
Suction Pump (n=3)	3 (100%)	1 (33%)	1 (33%)	0		
Pulse Oximeter (n=3)	3 (100%)	3 (100%)	2 (67%)	0		
Infant Transport Incubator (n=3)	3 (100%)	1 (33%)	2 (67%)	0		
Ventilator (n=2)	0	0	0	0		
Miscellaneous (n=5)	4 (80%)	3 (60%)	3 (60%)	0		

ECG signal when in the humid environment; however, unsynchronized defibrillation was possible. The unit operated normally when returned to ambient conditions.

All of the medical devices tested in the program passed the conducted susceptibility tests. This is probably the result of current isolation design consideration in medical devices to protect patients from inadvertent grounding.

Many devices produced electrical emissions on their power-lines that exceeded the military standard. These emissions could interfere with aircraft power circuits. Most of the medical devices tested in this program exceeded the radiated and conducted emissions standard for use in U.S. Army helicopters. Most of these failures involved weak electrical field strengths or narrow frequency bands that were not used by comunication or navigation radios in the air-

craft. In recognition of this, most of these devices obtained airworthiness releases and were successfully test flown in the UH-60 aircraft.

In a test of electromagnetic field strengths produced by the U.S. Army helicopters, a dramatic example of electromagnetic interference was produced. A monitor/defibrillator was operated with a simulated ECG signal in a UH-1 helicopter on battery power. When the FM radio transmitter in the aircraft was keyed, an interference pattern, similar in appearance to "atrial flutter," was seen on the ECG monitor (Fig. 2).

A suction pump and two infusion pumps were judged to produce sufficient emissions to be a potential hazard in the aircraft. They were not issued airworthiness releases and were not test flown. Another infusion pump was judged unsatisfactory because it always produced an "air-in-line" alarm during alti-




Figure 2. Example of electromagnetic interference in an ECG monitor on board an operating U.S. Army MEDEVAC helicopter.

tude chamber tests. Finally, a noninvasive blood pressure monitor could not differentiate the Kortkoff sounds of the blood pressure in the high ambient background noise produced by the turbine engines of the Black Hawk helicopter.

Conclusions

The lives of patients and the safety of the aircraft depend on the proper

operation of medical devices. This includes operation in the harsh environment produced by extremes of temperature, humidity, altitude and vibration. In addition, the sophisticated electronics of aircraft systems and individual medical devices may not be tolerant of stray electromagnetic signals. Interference can render a medical device or aircraft system unusable or produce more

insidious changes like the "atrial flutter" seen on an ECG monitor.

When a medical device or aircraft system fails unexpectedly, the operating environment and possibility of interference could be the culprit. Laboratory evaluation of the characteristics of each medical device provides useful information to predict the actual performance of the device in air medical transport service.

References

- Department of Defense: Environmental Test Methods and Engineering Guidelines. MIL-STD-810D, Washington, DC, 1983.
- Bronaugh EL, Lambdin WS: Electromagnetic Interference Test Methodology and Procedures. Vol. 6. Gainesville, Va., Interference Control Technologies Inc., 1988.
- Clarke CA: Avionics electromagnetic interference immunity and environment. In: Proceedings—IEEE/AIAA 7th Digital Avionics Systems Conference. Fort Worth, 1986, pp 633-640.
- Department of Defense: EMI Characteristics, Requirements for Equipment. MIL-STD-461C, Washington, DC, 1986.
- 5. Department of Defense: EMI Characteristics, Measurement of. MIL-STD-462, Washington, DC, 1971.
- Mitchell GW, Adams JE: Technical Test and Evaluation of Aeromedical Equipment. LR-88-16-1-2, Fort Rucker, Ala., U.S. Army Aeromedical Research Laboratory, 1988.
- Bruckart JE: Radiated electric field measurements in U.S. Army helicopters. Aviat Space Environ Med 1992; 63: pp 1019-1023.

Editor's Note: The U.S. Army cannot publish a list of manufacturers involved in the tests described in this paper. However, the information on any specific piece of equipment is available to individuals under the Freedom of Information Act. Please write to Dr. Bruckart in care of. U.S. Army Aeromedical Research Laboratory, Fort Rucker, AL, 36362-5292.

Initial distribution

Commander, U.S. Army Natick Research, Development and Engineering Center ATTN: SATNC-MIL (Documents Librarian) Natick, MA 01760-5040 Library
Naval Submarine Medical Research Lab
Box 900, Naval Sub Base
Groton, CT 06349-5900

Chairman
National Transportation Safety Board
800 Independence Avenue, S.W.
Washington, DC 20594

Commander
10th Medical Laboratory
ATTN: Audiologist
APO New York 09180

Naval Air Development Center Technical Information Division Technical Support Detachment Warminster, PA 18974

Commanding Officer, Naval Medical Research and Development Command National Naval Medical Center Bethesda, MD 20814-5044

Deputy Director, Defense Research and Engineering ATTN: Military Assistant for Medical and Life Sciences Washington, DC 20301-3080

Commander, U.S. Army Research Institute of Environmental Medicine Natick, MA 01760 Executive Director, U.S. Army Human Research and Engineering Directorate ATTN: Technical Library Aberdeen Proving Ground, MD 21005

Commander
Man-Machine Integration System
Code 602
Nava! Air Development Center
Warminster, PA 18974

Commander
Naval Air Development Center
ATTN: Code 602-B
Warminster, PA 18974

Commanding Officer Armstrong Laboratory Wright-Patterson Air Force Base, OH 45433-6573

Director Army Audiology and Speech Center Walter Reed Army Medical Center Washington, DC 20307-5001

Commander/Director
U.S. Army Combat Surveillance
and Target Acquisition Lab
ATTN: SFAE-IEW-JS
Fort Monmouth, NJ 07703-5305

Director
Federal Aviation Administration
FAA Technical Center
Atlantic City, NJ 08405

Commander, U.S. Army Test and Evaluation Command Directorate for Test and Evaluation ATTN: AMSTE-TA-M (Human Factors Group) Aberdeen Proving Ground, MD 21005-5055

Naval Air Systems Command Technical Air Library 950D Room 278, Jefferson Plaza II Department of the Navy Washington, DC 20361

Director
U.S. Army Ballistic
Research Laboratory
ATTN: DRXBR-OD-ST Tech Reports
Aberdeen Proving Ground, MD 21005

Commander
U.S. Army Medical Research
Institute of Chemical Defense
ATTN: SGRD-UV-AO
Aberdeen Proving Ground,
MD 21010-5425

Commander
USAMRDALC
ATTN: SGRD-RMS
Fort Detrick, Frederick, MD 21702-5012

Director
Walter Reed Army Institute of Research
Washington, DC 20307-5100

HQ DA (DASG-PSP-O) 5109 Leesburg Pike Falls Church, VA 22041-3258

Harry Diamond Laboratories ATTN: Technical Information Branch 2800 Powder Mill Road Adelphi, MD 20783-1197

U.S. Army Materiel Systems
Analysis Agency
ATTN: AMXSY-PA (Reports Processing)
Aberdeen Proving Ground
MD 21005-5071

U.S. Army Ordnance Center and School Library Simpson Hall, Building 3071 Aberdeen Proving Ground, MD 21005

U.S. Army Environmental
Hygiene Agency
ATTN: HSHB-MO-A
Aberdeen Proving Ground, MD 21010

Technical Library Chemical Research and Development Center Aberdeen Proving Ground, MD 21010-5423

Commander
U.S. Army Medical Research
Institute of Infectious Disease
ATTN: SGRD-UIZ-C
Fort Detrick, Frederick, MD 21702

Director, Biological Sciences Division Office of Naval Research 600 North Quincy Street Arlington, VA 22217 Commandant

U.S. Army Aviation

Logistics School ATTN: ATSQ-TDN

Fort Eustis, VA 23604

Headquarters (ATMD)
U.S. Army Training
and Doctrine Command
ATTN: ATBO-M

Fort Monroe, VA 23651

IAF Liaison Officer for Safety USAF Safety Agency/SEFF 9750 Avenue G, SE Kirtland Air Force Base

Naval Aerospace Medical Institute Library Building 1953, Code 03L Pensacola, FL 32508-5600

NM 87117-5671

Command Surgeon HQ USCENTCOM (CCSG) U.S. Central Command MacDill Air Force Base, FL 33608

Director

Directorate of Combat Developments

ATTN: ATZQ-CD Building 515

Fort Rucker, AL 36362

U.S. Air Force Institute
of Technology (AFIT/LDEE)

Building 640, Area B Wright-Patterson

Air Force Base, OH 45433

Henry L. Taylor Director, Institute of Aviation University of Illinois-Willard Airport Savoy, IL 61874 Chief, National Guard Bureau

ATTN: NGB-ARS
Arlington Hall Station

111 South George Mason Drive

Arlington, VA 22204-1382

Commander

U.S. Army Aviation and Troop Command

ATTN: AMSAT-R-ES 4300 Goodfellow Bouvelard St. Louis, MO 63120-1798

U.S. Army Aviation and Troop Command Library and Information Center Branch

ATTN: AMSAV-DIL

4300 Goodfellow Boulevard

St. Louis, MO 63120

Federal Aviation Administration

Civil Aeromedical Institute

Library AAM-400A

P.O. Box 25082

Oklahoma City, OK 73125

Commander

U.S. Army Medical Department

and School

ATTN: Library

Fort Sam Houston, TX 78234

Commander

U.S. Army Institute of Surgical Research

ATTN: SGRD-USM

Fort Sam Houston, TX 78234-6200

AAMRL/HEX

Wright-Patterson

Air Force Base, OH 45433

Air University Library

(AUL/LSE)

Maxwell Air Force Base, AL 36112

Product Manager
Aviation Life Support Equipment
ATTN: SFAE-AV-LSE
4300 Goodfellow Boulevard
St. Louis, MO 63120-1798

Commander and Director
USAE Waterways Experiment Station
ATTN: CEWES-IM-MI-R,
CD Department
3909 Halls Ferry Road
Vicksburg, MS 39180-6199

Commanding Officer Naval Biodynamics Laboratory P.O. Box 24907 New Orleans, LA 70189-0407

Assistant Commandant
U.S. Army Field Artillery School
ATTN: Morris Swott Technical Library
Fort Sill, OK 73503-0312

Mr. Peter Seib Human Engineering Crew Station Box 266 Westland Helicopters Limited Yeovil, Somerset BA20 2YB UK

U.S. Army Dugway Proving Ground Technical Library, Building 5330 Dugway, UT 84022

U.S. Army Yuma Proving Ground Technical Library Yuma, AZ 85364

AFFTC Technical Library 6510 TW/TSTL Edwards Air Force Base, CA 93523-5000 Commander
Code 3431
Naval Weapons Center
China Lake, CA 93555

Aeromechanics Laboratory
U.S. Army Research and Technical Labs
Ames Research Center, M/S 215-1
Moffett Field, CA 94035

Sixth U.S. Army ATTN: SMA Presidio of San Francisco, CA 94129

Commander
U.S. Army Aeromedical Center
Fort Rucker, AL 36362

Strughold Aeromedical Library
Document Service Section
2511 Kennedy Circle
Brooks Air Force Base, TX 78235-5122

Dr. Diane Damos
Department of Human Factors
ISSM, USC
Los Angeles, CA 90089-0021

U.S. Army White Sands
Missile Range
ATTN: STEWS-IM-ST
White Sands Missile Range, NM 88002

U.S. Army Aviation Engineering
Flight Activity
ATTN: SAVTE-M (Tech Lib) Stop 217
Edwards Air Force Base, CA 93523-5000

Ms. Sandra G. Hart Ames Research Center MS 262-3 Moffett Field, CA 94035 Commander
USAMRDALC
ATTN: SGRD-UMZ
Fort Detrick, Frederick, MD 21702-5009

Commander
U.S. Army Health Services Command
ATTN: HSOP-SO
Fort Sam Houston, TX 78234-6000

U. S. Army Research Institute Aviation R&D Activity ATTN: PERI-IR Fort Rucker, AL 36362

Commander U.S. Army Safety Center Fort Rucker, AL 36362

U.S. Army Aircraft Development
Test Activity
ATTN: STEBG-MP-P
Cairns Army Air Field
Fort Rucker, AL 36362

Commander
USAMRDALC
ATTN: SGRD-PLC (COL R. Gifford)
Fort Detrick, Frederick, MD 21702

TRADOC Aviation LO Unit 21551, Box A-209-A APO AE 09777

Netherlands Army Liaison Office Building 602 Fort Rucker, AL 36362

British Army Liaison Office Building 602 Fort Rucker, AL 36362 Italian Army Liaison Office Building 602 Fort Rucker, AL 36362

Directorate of Training Development Building 502 Fort Rucker, AL 36362

Chief
USAHEL/USAAVNC Field Office
P. O. Box 716
Fort Rucker, AL 36362-5349

Commander, U.S. Army Aviation Center and Fort Rucker ATTN: ATZQ-CG Fort Rucker, AL 36362

Chief
Test & Evaluation Coordinating Board
Cairns Army Air Field
Fort Rucker, AL 36362

Canadian Army Liaison Office Building 602 Fort Rucker, AL 36362

German Army Liaison Office Building 602 Fort Rucker, AL 36362

French Army Liaison Office USAAVNC (Building 602) Fort Rucker, AL 36362-5021

Australian Army Liaison Office Building 602 Fort Rucker, AL 36362

Dr. Garrison Rapmund 6 Burning Tree Court Bethesda, MD 20817 Commandant, Royal Air Force Institute of Aviation Medicine Farnborough, Hampshire GU14 6SZ UK

Defense Technical Information Cameron Station, Building 5 Alexandra, VA 22304-6145

Commander, U.S. Army Foreign Science and Technology Center AIFRTA (Davis) 220 7th Street, NE Charlottesville, VA 22901-5396

Commander
Applied Technology Laboratory
USARTL-ATCOM
ATTN: Library, Building 401
Fort Eustis, VA 23604

Commander, U.S. Air Force
Development Test Center
101 West D Avenue, Suite 117
Eglin Air Force Base, FL 32542-5495

Aviation Medicine Clinic TMC #22, SAAF Fort Bragg, NC 28305

Dr. H. Dix Christensen Bio-Medical Science Building, Room 753 Post Office Box 26901 Oklahoma City, OK 73190

Commander, U.S. Army Missile
Command
Redstone Scientific Information Center
ATTN: AMSMI-RD-CS-R
/ILL Documents
Redstone Arsenal, AL 35898

Director Army Personnel Research Establishment Farnborough, Hants GU14 6SZ UK

U.S. Army Research and Technology Laboratories (AVSCOM) Propulsion Laboratory MS 302-2 NASA Lewis Research Center Cleveland, OH 44135

Commander
USAMRDALC
ATTN: SGRD-ZC (COL John F. Glenn)
Fort Detrick, Frederick, MD 21702-5012

Dr. Eugene S. Channing 166 Baughman's Lane Frederick, MD 21702-4083

U.S. Army Medical Department and School USAMRDALC Liaison ATTN: HSMC-FR Fort Sam Houston, TX 78234

Dr. A. Kornfield 895 Head Street San Francisco, CA 94132-2813

NVESD AMSEL-RD-NV-ASID-PST (Attn: Trang Bui) 10221 Burbeck Road Fort Belvior, VA 22060-5806

CA Av Med HQ DAAC Middle Wallop Stockbridge, Hants S020 8DY UK Dr. Christine Schlichting Behavioral Sciences Department Box 900, NAVUBASE NLON Groton, CT 06349-5900

Commander, HQ AAC/SGPA Aerospace Medicine Branch 162 Dodd Boulevard, Suite 100 Langley Air Force Base, VA 23665-1995

Commander Aviation Applied Technology Directorate ATTN: AMSAT-R-TV Fort Eustis, VA 23604-5577

COL Yehezkel G. Caine, MD Surgeon General, Israel Air Force Aeromedical Center Library P. O. Box 02166 I.D.F. Israel Director
Aviation Research, Development
and Engineering Center
ATTN: AMSAT-R-Z
4300 Goodfellow Boulevard
St. Louis, MO 63120-1798

Commander
USAMRDALC
ATTN: SGRD-ZB (COL C. Fred Tyner)
Fort Detrick, Frederick, MD 21702-5012